Official copies of these procedures are maintained at this website.

Before using a printed copy, verify that it is the most current version by checking the document issue date on this website. Signed copies of these official procedures are maintained at the Training Office.

C-A OPERATIONS PROCEDURES MANUAL

ATTACHMENT

4.56.aj RHIC Zone 2z2 Sweep Checklist

Text Pages 2 through 4

C-A OPM Procedures in which this Attachment is used.

4.5	6		
	Hand Pr	rocessed Changes	
HPC No.	<u>Date</u>	Page Nos.	<u>Initials</u>
Approved:	Signature	e On File	
	Collider-Acc	elerator Department Cha	irman Date
P. Ingrassia, W. MacKay			
C-A-OPM-ATT 4.56.aj (Y)		1	Revision 00

October 5, 2000

RHIC Zone 2z2 Sweep Checklist

Team leader (TL)	_ Sweeper#2 (32)
Timo:	Data


Warning:

IF any workers are encountered during the sweep, **THEN** contact the OC to see if the sweep should be aborted. Workers shall leave the enclosure **WITH** the sweep team. **IF** the workers crash out of the enclosure **AND** do not exit with the sweep team, **THEN** the sweep shall be restarted.

Prerequisites

T---- 1-- 1-- (TI)

- Two persons to perform the sweep,
- At least one sweeper not restricted from working at heights over five feet.
- RHIC Zone 2z2 Sweep Checklist (three pages)
- Required Tools: at least one flashlight,
- Padlock for 2MD3 (one may be in place)
- Walkie-talkies
- All Doors closed THEN 2Z2 set to Controlled Access
- Keys: Sweep Reset key S/R015, Controlled Access key CA014, key for padlock



Note:

References to positions in the tunnel are made using the RHIC magnets. The identity of the local magnet can be determined by looking up at the "lower" cable tray and reading the magnet name on a blue (B) or yellow (Y) label. For example, the convention used is: I05Q17 (Inside, Q17) or O-05Q17 (Outside, Q17). References are for inside locations and are visible only by the Team Leader

<u>check</u>

_1. Sweep team enters 2z2 after TL requests simultaneous release from MCR (2GE2 is the recommended entry door).

CONTINUED ON REVERSE SIDE

C-A-OPM-ATT 4.56.aj (Y)

Revision 00 October 5, 2000

2.	TL opens 2GE2 gate by turning the CA015 key clockwise, in the Controlled Access key-switch
	while Operator in MCR presses simultaneous release for 2GE2.
3.	Sweep Team passes through 2GE2 door.
	Note:
	Gate 2MD3 must be reset before the sweep may begin
ı	
4	Sweep team walks to 2MD3.
5	IF 2MD3 is not reset AND the door is not padlocked, THEN TL opens the door and shines the flashlight
	down the tunnel to search for persons. IF any object in the tunnel blocks the view THEN the TL shall enter
	and verify that no one is inside.
6	TL closes and padlocks the door and resets the gate using the S/R015 key in the RESET keyswitch.
7	Observe the yellow RESET lamp is lighted.
8	TL crosses under the accelerators to the inside of the tunnel while S2 remains outside.
9	Sweep team walks to 3GI1 at the far (3 o'clock) end of the 2z2 zone.
10	S2 stands static watch at 3GI1.
	TL walks down labyrinth to 2ED1 door.
12	TL resets gate 2ED1 using the S/R015 key in the RESET keyswitch.
13	TL observes the yellow RESET lamp is lighted
14	TL STARTS SWEEP by turning the S/R015 key CW in the SWEEP key-switch (2CS6)
15	TL observes AREA SECURED lamp blink once.
16	TL confirms overhead barrier is in place near 2ED1 gate
17	TL sweeps out the labyrinth and rejoins S2.
18	TL stands static watch while S2 climbs yellow stairs and searches fan vents and the
	space above the cable trays.
19	S2 returns to the outside of the tunnel and stands static watch.
20	TL goes to check station 2CS5 in the 1003B Alcove.
	TL sets second check station (2CS5) by turning S/R015 key in the SWEEP keyswitch.
	TL observes AREA SECURED lamp blink once.
	TL searches all the equipment racks, sweeps out the alcove, and rejoins S2.
	Sweep team sweeps Counter Clockwise (CCW) around RHIC.
	TL stops to check the Exhaust Fan Vent Barrier at I-02Q17.
	Sweep team sweeps Counter Clockwise (CCW) around RHIC.
	S2 stands static watch at the electrical services alcove opposite T-02Q13.
	TL walks to the ladder at 2EL1 in alcove 1003A.
29	IF there is no mirror to verify no one is on the landing at the top of the ladder, THEN TL
•	must climb the ladder to verify no one is on the landing and to check that 2EL1 door is closed.
	TL resets gate 2EL1 using the S/R015 key in the RESET keyswitch at the bottom of the ladder.
	IF 2EL1 will not reset THEN TL climbs the ladder, closes 2EL1, then repeats step 30.
	TL observes GATE RESET lamp lights after RESET.
	TL sets third check station (2CS3) by turning S/R015 key in the SWEEP keyswitch.
	TL observes AREA SECURED lamp blink once.
	TL searches all the equipment racks,
	TL goes to check station 2CS4 at the far corner of the alcove.
	TL sets fourth check station (2CS4) by turning S/R015 key in the SWEEP keyswitch.
	TL observes AREA SECURED lamp blink once.
	TL sweeps out the alcove, and rejoins S2.
40	TL confirms fan vent barrier is in place on the far side of the tunnel (above S2) and overhead barrier is in
A 1	place. Super team supers Counter Cleakwise (CCW) around PHIC
41	Sweep team sweeps Counter Clockwise (CCW) around RHIC.

CONTINUED ON NEXT SHEET

42	TL stops to check the Exhaust Fan Vent Barriers at I-02D10.
43	Sweep team sweeps Counter Clockwise (CCW) around RHIC.
44	Team Leaser checks exhaust fan vent barrier at I-02Q6
45	TL checks exhaust fan vent barrier next to S2WB1 bake out switch box
46	TL checks Exhaust Fan Access Door padlocks at I-02D5
46	Sweep team sweeps Counter Clockwise (CCW) around RHIC.
47	Sweep team sweeps to gate 2GI1.
48	IF not reset, TL resets 2GI1 gate using the S/R015 key in the RESET keyswitch on the 2GI1-I gate box.
49	Observe the yellow GATE RESET lamp is lighted.
50	TL sets fifth check station (2CS1) by turning S/R015 key in the SWEEP keyswitch.
	TL observes AREA SECURED lamp blink once.
52	S2 crosses under the accelerators to join TL.
53	Sweep Team sweeps out the labyrinth to gate 2GE2.
54	TL ends sweep by turning S/R015 key in the SWEEP keyswitch at 2CS2.
55	Observe the yellow AREA SECURED indicator remains lighted.
	TL contacts MCR for simultaneous release for gate 2GE2.
	Sweep Team sweeps out zone 2z2 through 2GE2.
58	TL observes the yellow AREA SECURED lamp is lighted.
59	TL contacts MCR and confirms that gates are reset and 2z2 zone indicates sweep is good.
	Note: IF the AREA SECURED, and GATE RESET lamps are not lit THEN contact MCR to verify sweep is good and gates(s) are reset.
60	After returning keys to keytree in MCR, TL RESETS the RCA gate 2GE2 using the RHIC PanelView in the
	MCR.
61	After verifying that all information is filled out completely, TL files the checklist in FY_xx Sweep Log binder.